



ITwiz Computer Support
Unit #228, 1088 Sunset Drive
Kelowna, V1Y 9W1
Business # 83191 2092 RT0001
February 22, 2011
Invoice # - 9241

Tammy Jones

Coldstream,

Date	Work done	Total
	Getting master boot record error	
Feb 22	Checked internal cables Changed BIOS settings Scanned hard drive for errors	\$120.00
	Total Time	\$120.00
	HST (12%)	\$14.40
	Total	\$134.40

Invoice to be paid when services rendered
Thank you